

FIG. 1






FIG. 2




FIG. 3




FIG. 4




FIG. 5

Check	OPT #	Description
<input type="checkbox"/>	0	Thread_Mate
<input type="checkbox"/>	1	Top_Flat_Surface
<input type="checkbox"/>	2	Carl_Bottom

FIG. 6

Check	OPT #	Description	Value
<input type="checkbox"/>	0	Pan	1
<input type="checkbox"/>	1	Hex	2
<input type="checkbox"/>	2	Socket	3

FIG. 7

506 706

402 402

504

Link Definition

SAVE

Name: Head_Type
ID: 2

Check	OPT #	Descr.	Value
<input checked="" type="checkbox"/>	0	Pan	1
<input type="checkbox"/>	1	Hex	2
<input type="checkbox"/>	2	Socket	3

606 804 610 704

Name: Bolt_Diameter
ID: 3

Check	OPT #	Descr.	Value
<input type="checkbox"/>	0	2 mm	2
<input checked="" type="checkbox"/>	1	3 mm	3
<input type="checkbox"/>	2	5 mm	5
<input checked="" type="checkbox"/>	3	10 mm	10

606 608 806 704 800 802

FIG. 8

402 506

504

Link Definition

SAVE

202

Name: Bolt_Diameter
ID: 3

Check	OPT #	Descr.	Value
<input type="checkbox"/>	0	2 mm	2
<input type="checkbox"/>	1	3 mm	3
<input checked="" type="checkbox"/>	2	5 mm	5
<input type="checkbox"/>	3	10 mm	10

804

Name: Bolt
ID: 1

Check	OPT #	Descr.	Dim. Val.
<input type="checkbox"/>	0	Diameter	0.500
<input type="checkbox"/>	1	Length	2
<input type="checkbox"/>	2	Length	4
<input checked="" type="checkbox"/>	3	Length	5
<input type="checkbox"/>	4	Length	6

800 806

FIG. 9

Name: Nut
ID: 4

Surface	Axis	Parameter	Dimensions
<input checked="" type="checkbox"/>	0	Thread_Mate	
<input type="checkbox"/>	1	Top_Mate	

Name: Bolt
ID: 1

Surface	Axis	Parameter	Dimensions
<input checked="" type="checkbox"/>	0	Thread_Mate	
<input type="checkbox"/>	1	Top_Flat_Surface	
<input type="checkbox"/>	2	Carl_Bottom	

Thread_Mate

Mate

Align

Thread_Mate

.125

Center

T_POS2

Align

Thread_Mate

.125

Center

FIG. 10

506

402

504

Link Definition

202

SAVE

Name: Head_Type

ID: 2

Check	OPT #	Descr.	Value
<input type="checkbox"/>	0	Pan	1
<input checked="" type="checkbox"/>	1	Hex	2
<input type="checkbox"/>	2	Socket	3

Name: Bolt

ID: 1

Check	OPT #	Descr.	P. Value	P. Type
<input type="checkbox"/>	0	Head_Type	1	INT
<input checked="" type="checkbox"/>	1	Head_Type	2	INT
<input type="checkbox"/>	2	Head_Type	3	INT
<input type="checkbox"/>	3	Head_Type	4	INT

FIG. 11




FIG. 12




FIG. 13




FIG. 14




FIG. 17

1502

Question

What type of thread on bolt?

Answers

None

Length of bolt?

19 mm 20 mm

22 mm 25 mm

How many fan blades?

3 4 8

Customer ID?

Post Processing Options

☐ Print ☐ Display ☐ Save ☐ Email

1506

1508

1510

1500

1504

FIG. 15

1502

1504

Question

What type of thread on bolt?

Answers

Fully threaded ▾ 1604

Length of bolt? ☒ 22 mm ☐ 25 mm

What type of material for fan? ☐ Hardened steel ☐ Stainless steel

Customer ID?

Post Processing Options

☐ Print ☐ Display ☐ Save ☐ Email


1506

1508

1510

1500

FIG. 16






FIG. 19